

spare parts list and drawing K3.97M




5.958-97

K 39X M

1.0 PIECE PARTS

WWW.PRESSUREPARTS.COM



This drawing covers models with part numbers...

1.423-104.0	1.423-234.0
1.423-105.0	1.423-235.0
1.423-110.0	

Caution: Electrical Hazard. Repairs or attempted repairs by untrained persons may result in damage to the pressure washer and/or personal injury as well as voiding any warranty. Customers are strongly advised to have their machine examined by a trained professional at an authorized Kärcher service location.


1	9.036-781.0 COVER K 3.97M / / 1.423-114.0	1
1	9.037-016.0 COVER K 3.99M / / 1.423-254.0 / -300.0	1
2	9.011-608.0 CHASSIS FOR TANK VERSION 1	1
2	9.011-857.0 CHASSIS FOR TANK VERSION 2	1
2	9.011-909.0 CASSIS FOR VERSIONS WITHOUT TANK	1
3	9.036-737.0 BOLT	1

spare parts list and drawing

5.958-976 /

K 39X M /

1.0 PIECE PARTS




4	9.086-173.0	SCREW	8
5	9.036-731.0	ACCESSORIES BRACKET	1
6	9.036-724.0	HANDLE	1
7	9.036-727.0	PLUG	2
8	9.036-738.0	TURNING KNOB	1
9	9.001-260.0	WHEEL SET	1
		SET OF 2 PIECES	
10	9.084-055.0	CABLE	1
		-EUR- /	
10	9.084-064.0	CABLE	1
		-GB- /	

spare parts list and drawing

5.958-976 /

K 39X M /

1.0 PIECE PARTS




10	9.084-065.0 CABLE -AUS/NZ- /	1
10	9.084-070.0 CABLE -CH- /	1
11	9.036-728.0 RM-TANK K 39X VERSION 1 /	1
12	9.048-067.0 CAP OF A TANK VERSION 1 /	1
13	9.036-723.0 SUPPORT	1
14	9.036-729.0 FILTER VERSION 1 /	1

spare parts list and drawing

5.958-976 /

K 39X M /

1.0 PIECE PARTS




15	9.036-722.0	MOULDED PART	1
16	9.036-730.0	COVERING CAP	1
17	9.011-711.0	FILTER	1
	VERSION 2 /		
18	9.036-893.0	RM-TANK K3./4.9XMD	1
	VERSION 2 /		

spare parts list and drawing

5.958-976

K 39X M

4.2 JET PIPE




1	2.640-589.0	BRUSH	1
2	2.883-111.0	SPARE PARTS KIT	3
3	9.011-421.0	ROTARY NOZZLE	1
5	6.303-122.0	OVAL HEAD SCREW	6
6	9.036-402.0	HANDLES	1
7	9.036-403.0	PIPE	1
8	6.362-534.0	GASKET	1
9	4.762-238.0	NOZZLE CAP	1
10	4.762-065.0	ROTATING BRUSH	1
11	4.760-482.0	QUADRUPLE NOZZLE	1

spare parts list and drawing

5.958-976 /

K 39X M /

4.2 JET PIPE




12	2.640-212.0	SUCTION APPARATUS	1
13	4.760-544.0	VPS K5 0287VERPACKT	1
14	6.389-092.0	LENGTHENING PIECE (HOSE)	1
15	2.880-296.0	SPARE PARTS KIT	1

spare parts list and drawing

5.958-976

K 39X M

4.1 TRIGGER GUN




0	4.775-389.0 PISTOL-M VERSION 1 /	1
0	4.775-423.0 PISTOL-M VERSION 2 /	1
1	5.037-137.0 CLAMP	1
2	5.332-464.0 PRESSURE SPRING	1
3	6.363-198.0 GASKET	1
4	6.390-499.0 HD-M-HOSE 7,5/14 MPA	1
5	2.880-296.0 SPARE PARTS KIT	1

spare parts list and drawing

5.958-976 /

K 39X M /

3.0 MOTOR




0	9.001-213.0	MOTOR	1
1	6.964-090.0	FAN HOUSING	1
2	7.304-395.0	HEXAGONAL HEAD SCREW	1
3	9.039-102.0	BLOWER WHEEL	1
4	6.964-092.0	FAT	1
5	6.964-096.0	END PLATE	1
6	9.078-004.0	ROTARY SHAFT SEAL	1
7	7.401-136.0	BALL BEARING	1
8	9.086-153.0	OVAL HEAD SCREW	4
9	9.086-169.0	SCREW	1

spare parts list and drawing

5.958-976 /

K 39X M /

3.0 MOTOR




10	9.039-090.0	SWASH PLATE	1
11	7.312-233.0	SERRATED LOCK WASHER	1
12	5.363-466.0	JOINT RING	1

spare parts list and drawing

5.958-976 /

K 39X M /

2.2 HOUSING




2	9.047-023.0	SPRING	3
3	9.001-102.0	PISTON	3
4	9.081-373.0	GASKET	1
5	9.001-101.0	HOUSING	1
6	6.964-026.0	GROOVED RING	3
7	7.306-042.0	CHEESE HEAD SCREW	4

spare parts list and drawing

5.958-976

K 39X M

2.1 HOUSING




1	9.001-103.0	SPARE PARTS SET	1
2	9.001-110.0	MOULDED PART	3
4	9.081-421.0	GASKET	1
5	9.001-149.0	VENTILSET	3
6	9.039-148.0	CLAMP	1
7	9.036-703.0	CONNECTION	1
8	9.001-187.0	SPARE PARTS SET	1
9	6.389-870.0	CONNECTION	1
10	9.036-705.0	SUCTION CONNECTION	1
11	9.036-444.0	SLEEVE	1

spare parts list and drawing

5.958-976

K 39X M

2.1 HOUSING




12	6.362-151.0	GASKET	1
14	7.311-569.0	SQUARE NUT	1
15	6.388-216.0	HOSE	1
	TO ORDER AS CUT GOODS		
16	5.731-609.0	FILTER	1
17	9.036-322.0	SUPPORTING DISK	3
18	6.362-875.0	GROOVED RING	3
20	9.001-105.0	ZYLINDERKOPFSET	1
24	9.081-418.0	FORM SEAL	1
25	9.001-104.0	SPARE PARTS SET	1

spare parts list and drawing

5.958-976

K 39X M

2.1 HOUSING



26	9.039-117.0	COVER	1
27	7.306-042.0	CHEESE HEAD SCREW	4
32	9.001-108.0	INJECTOR	1
34	9.047-026.0	SPRING	1
35	9.001-107.0	CAGE	1
38	9.001-106.0	JOINING PIECE	1

spare parts list and drawing


5.958-976

/

K 39X M

/

5.0 ELECTRIC BOX



1	9.001-100.0	COVER	1
2	7.303-031.0	SCREW	1
3	9.085-035.0	CAPACITOR	1
4	9.036-348.0	HOUSING	1
5	6.362-870.0	GASKET	1
6	9.048-011.0	BUSH	1
7	9.086-153.0	OVAL HEAD SCREW	2
8	9.036-384.0	SWITCH LEVER	1
9	9.085-034.0	SWITCH	1
15	9.036-725.0	SWITCH KNOB	1